

Siemens Enterprise Communications

Release Notes

Release Notes Version: 5.0

Product Name: *OpenStage 15 TDM*

Product Version: V2

Software Release is identified by Version: V2 R0.8.0

Major Release Minor Release Fix Release Hotfix Release

Production Version:

System:		
File type	Product Item Number / File name	Size
Binary	OS_15_TDM_V2_R0_8_0.bin	550 KB

Export Control Classification Data AL: N ECCN: 5D002ENC3

Field Trial: eeQS: Limited Availability: General Availability:

Notice:

This document contains confidential information that is proprietary to Siemens Enterprise Communications GmbH & Co. KG. No part of its contents may be used, copied, disclosed, or conveyed to any party in any manner whatsoever without prior consent.

DECLARATION DATE: Date : 2012-01-27

DELIVERABLES: Full Release: Delta Release:

Abstract:

This document provides general information about the release, generics, and other relevant notes for the corresponding product and its correction versions. This document also lists and describes the known issues, restrictions, and workarounds.

Siemens Enterprise Communications GmbH & Co. KG is a Trademark Licensee of Siemens AG

Siemens Enterprise Communications GmbH & Co. KG
Hofmannstr. 51
D-81379 München
Bundesrepublik Deutschland

www.siemens-enterprise.com

Table of Contents

1	HISTORY OF CHANGE	3
1.1	RELEASE NOTES HISTORY	3
1.2	PRODUCT VERSION HISTORY	3
2	IMPORTANT INFORMATION	3
2.1	INSTALLATION	3
2.2	UPGRADE / UPDATE	4
2.3	FALLBACK	4
2.4	SECURITY CONSIDERATIONS	4
2.5	SPECIAL SETTINGS AND INSTRUCTIONS	4
2.5.1	<i>Keymodul</i>	4
3	KNOWN ISSUES	4
3.1	RESTRICTIONS	4
3.2	WORKAROUNDS / HINT	4
4	CHANGES	4
4.1	NEW IN THIS RELEASE	4
4.2	IMPLEMENTED CHANGE REQUESTS	5
4.3	ISSUES RESOLVED	5
5	HARDWARE AND SOFTWARE COMPATIBILITY	5
5.1	HARDWARE REVISIONS	5
5.1.1	<i>Phones</i>	5
5.2	FIRMWARE RELEASES	5
5.3	LOADWARE RELEASES	5
5.4	SOFTWARE RELEASES	6
5.5	OPERATING SYSTEMS (INCLUDING SECURITY ALERTS)	6
5.6	COMPLIANT PRODUCTS (COMPATIBILITY MATRIX)	6
6	SERVICE INFORMATION	6
6.1	MANAGEMENT INFORMATION BASE	6
6.2	LICENSE MANAGEMENT	6
7	ATTACHMENT	7

1 History of change

1.1 Release notes history

Version	Date	Changes
1.0	01.04.10	Release of SW version 15 TDM V2R0.2.0 as GA
2.0	07.09.10	Release of SW version 15 TDM V2R0.3.0 as GA
3.0	06.05.11	Release of SW version 15 TDM V2R0.5.0 as GA
3.1	16.06.11	Add information about HP4K Patches V4
3.2	25.08.11	Correction at Compliant Products
4.0	02.09.11	Release of SW version 15 TDM V2R0.6.0 as GA
5.0	27.01.12	Release of SW version 15 TDM V2R0.8.0 as GA

1.2 Product version history

List of all released Software Versions since Major Software Release (M3), i.e. all Software Releases in PRISMA/SWS having been released within this Product version:

Software version (e.g. Vx[.y] Rm.f.h)	Production version (e.g. APS)	Date	Remarks
V2 R0.2.0	OpenStage 15 TDM	01.04.10	
V2 R0.3.0	OpenStage 15 TDM	07.09.10	
V2 R0.5.0	OpenStage 15 TDM	06.05.11	
V2 R0.6.0	OpenStage 15 TDM	02.09.11	
V2 R0.8.0	OpenStage 15 TDM	27.01.12	

2 Important Information

2.1 Installation

The software can be installed via HiPathManager SW-transfer at H3K and via TSDM at H4k.

Important for SW upgrade at HiPath 4K via replication for scenarios with OST phone adapters:

The correction of I05136 in bind V2R0.8.0 has effect for SW upgrade via replication when this bind is just installed.

To install this bind itself we propose to make SW upgrade to V2R0.8.0 in scenarios with OST phone adapter via D-channel.

For software installation at H4K in special scenarios H4K Patches are necessary (see chapter 5.6)

2.2 Upgrade / Update

Not applicable for this product.

2.3 Fallback

Not applicable for this product.

2.4 Security Considerations

Not applicable for this product.

2.5 Special settings and instructions

2.5.1 Keymodul

Keymodules are not hot pluggable.

Only one OpenStage 15 keymodule is supported. No additional power supply is necessary.

3 Known issues

ICTS Ticket	MR / CQ	Summary	Work-around

3.1 Restrictions

3.2 Workarounds / Hint

4 Changes

4.1 New in this release

.

4.2 Implemented change requests

CR Number	MR / CQ	Summary

4.3 Issues resolved

ICTS Ticket	MR / CQ	Summary
		Slave Phone can't be used as source for B-channel replication
		SETUP should not be accepted for not matching calling number
		OS sends wrong value for the selected menu index
		DISCONNECT delayed for 10s when called for B-channel transfer

5 Hardware and software compatibility

This section lists the supported hardware and software for the OpenStage 15 TDM product.

5.1 Hardware revisions

5.1.1 Phones

Server model	Revision
OpenStage 15 TDM ice blue	S30817-S7301-A501-4 or higher
OpenStage 15 TDM lava	S30817-S7301-A503-1 or higher

5.2 Firmware releases

Not applicable for this product.

5.3 Loadware releases

Not applicable for this product.

5.4 Software releases

Product	Software Version	Release Date ¹	G-DMS Note
Phone software OpenStage 15 TDM	V2 R0.8.0	27.01.2012	

5.5 Operating systems (including security alerts)

Not applicable for this product.

5.6 Compliant products (compatibility matrix)

Product Family	Product	Preferred Software Versions		
		Version	Status	G-DMS Note
HiPath 3000	HiPath 3000 Server	V7 R6.10.0 or newer (2)	GA	
		V8 R6.1.0 or newer (2)	GA	
		V9 R1.1.0 or newer	GA	
HiPath 4000	HiPath 4000 Server	V4R4.3.0 or newer (1) (2)	GA	
		V5 R1.5.0 or newer	GA	
		V6 R1.10.0 or newer	GA	

(1) Necessary patches:

MSC22438 (included in Hotfix V4R4.3.15)

(For software installation at H4K: When the phone is master behind an OST Phone adapter and the slave is an analog endpoint)

(2) OpenStage Mode could not be used with versions less than HiPath 3000 V8 R4.0.13 or less than HiPath 4000 V4R4.2.0, there OptiPoint Mode is to configure.

6 Service information

6.1 Management information base

Product forwards SNMP traps according to a MIB:

Not applicable for this product.

6.2 License management

The OpenStage 15 TDM product is certified for the following:

Not applicable for this product.

CLS: CSC: Other Licensing: If you are using others, please describe below:

7 Attachment

Not applicable for this product.